Townsend Well Control | Authorized Repair Facility

CERTIFICATE

OF AUTHORIZATION



O5-005 Original License Date January 23, 2023 - Current Effective Period January 23, 2023 through January 23, 2025

License Number

Form #: **QF-05-12**, **Rev 3**Date Issued: **April 4**, **2022**



General Petroleum Holdings Pty Ltd

68 Yumborra Road, Dalby, Queensland, 4405, Australia

AUTHORIZED REPAIR FACILITY / NAME / ADDRESS

HAS SUCESSFULLY COMPLETED AN ASSESSMENT BY TOWNSEND WELL CONTROL (TWC) TO VERIFY ALL REQUIREMENTS HAVE BEEN FULFILLED TO QUALIFY AS A TWC AUTHORIZED REPAIR FACILITY. *
* SCAN OR CODE ABOVE FOR AUTHENTICATION

The Authorized Repair Facility (ARF) utilizes fundamental technical and design data, in addition to engineering assistance, required to perform repairs and/or remanufacturing services per API S53 and/or API-16AR guidelines on products listed on the TWC API Product Licenses. Under the strict supervision and coordination of TWC, the ARF may only issue the appropriate remanufacturing and test data (Data Book) and Certificates of Conformance (COCs) necessary to recertify the equipment.

TRAVIS STEHLING

General Manager - TWC

Man Stling

DAVID HATALA
OHSE Director